PROJECT: SRMS (S MCIU INSTALLED)
ASS'Y HOMENCEATURE: DEC PANEL

SYSTEM: DEC SUBSYSTEM ASS'Y P/N: 51140E391

___ SHEET: __1

FMEA REF.	FMEA REV.	NAME, OTY, & DRAWING REF. DESIGNATION	FAILURE HODE AND CAUSE	FAILURE EFFEC! ON END IEM	HDWR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
1400	3	289 POWER SUPPLY QTY-1 (ORBITER SYSTEM). PS 90128. ML 90128. ED 85511	MODE: LOSS OF 28V DC. CAUSE(S): (1) ANY 28V SWITCH CONTACT SHORTS TO CASE (MODE, BRAKE, SAFING).	MILL BLOW 2 AMP FUSE. LOSS OF PRIMARY POWER, GPC TERMINATES 1/O. MCTU SHUTS DOWN, ARM WILL BE HARDWIRE SAFED AND BRAKES WILL BE APPLIED. LIMPING END EFFECTOR CAPTURE. LOSS OF EE PRIMARY DRIVE MODES. WORST CASE LOSS OF MISSION LOSS OF PRIMARY MODES. REDUNDANT PATHS REMAINING BACKUP	DESIGN FEATURES ROTARY SWITCHES USED ON THE DEC PAMEL ARE HERMETICALLY SEALED, AND OF A MATURE AND PROVEN DESIGN. THESE SWITCHES ARE IN COMMON USE ON THE ORDITOR YEAR TO THE SPECIFICATION MC 452-0049 AND HAVE BEEN QUALIFIED TO THE REQUIREMENTS OF THIS SPECIFICATION. ELECTRICAL CONNECTIONS TO THE SWITCH ARE ACHIEVED BY MEANS OF A MATING PAIR OF MB TYPE CIRCULAR CONNECTORS USING CRIMP STYLE CONTACTS. WHEN CIT OS WITCH CONNECTORS USING CRIMP STYLE CONTACTS. WHEN CIT OS WITCH CONNECTORS USING CRIMP STYLE CONTACTS. WHEN CIT OS WITCH CONNECTORS USING CRIMP STYLE CONTACTS. WHEN CIT OS WITCH CONNECTORS USING CRIMP STYLE CONTUCTORS WE'N A POLYAMIDE INSULATION. THE MIRING HARNESS IS DESIGNED TO BE CAPABLE OF SEPARATE TESTING (FOR INSULATION RESISTANCE DELECTRIC STRENGIN, AND CONTINUITY). THIS SWITCH IS MOUNTED TO THE DRC PAMEL BY MEANS OF THREE 6-32 FASTENERS. AFTER INSTALLATION AND TOTAUNITY. THIS SWITCH IS MOUNTED TO THE DRC PAMEL BY MEANS OF THREE 6-32 FASTENERS. AFTER INSTALLATION AND TOTAUNITY. THIS SWITCH IS MOUNTED TO THE DRC PAMEL BY MEANS OF THREE 6-32 FASTENERS. AFTER INSTALLATION AND TOTAUNITY. THE SWITCH IS MOUNTED TO THE DRC PAMEL BY MEANS OF THREE 6-32 FASTENERS. AFTER WIS ALLATION AND TOTAUNITY. THE PART LEVEL OF THE OWN OF THE DRC PAMEL BY MEANS OF THE BASIC PAMEL STRUCTURE HAS DEMONSTRATED THAT THERE ARE NO RESONANCES IN THE RELEVANT VIBRATION RESIGN. THE BASIC PAMEL STRUCTURE HAS DEMONSTRATED THAT THERE ARE NO RESONANCES IN THE RELEVANT VIBRATION TESTING OF THE DRC PAMEL ASSEMBLY. APPLICATION ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING OF THE DRC PAMEL ASSEMBLY. APPLICATION ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING OF THE DRC PAMEL ASSEMBLY. APPLICATION ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING OF THE DRC PAMEL ASSEMBLY. APPLICATION ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING OF THE SESSUALE. CONTACT RESISTANCE, DUALIFICATION/CERTIFICATION AT RATED DC CURRENT, LEXAMORD AND FIRMAL PREPORMANCE TEST. TOGGLE SWITCH ENGLANDED HAS ACCEPTANCE TESTS WHICH INCLUDE PRE-ACCEPTANCE RUN-I

FMEA

REV.

3

REF.

1400

NAME, QTY, B DRAWING REF.

DESIGNATION

28V POWER

SUPPLY

(ORBITER

SYSTEM).

PS 90128.

WL 90128.

011-1

FAILURE MODE

LOSS OF 28V

CAUSE(S):

SULTCH

(1) ANY 28V

AND

CAUSE

MODE:

PROJECT: SRMS (-5 MCIU INSTALLED)
ASS'Y NOMENCLATURE: DEC PANEL

HDWR / FUNC. 2/1R

CRITICALITY

CONTINUITY).

FAILURE EFFECT

ON

END ITEM

WILL BLOW 2 AMP

LOSS OF PRIMARY

TERMINATES 1/O.

POWER. GPC

HCIU SHUTS DOWN. ARM WILL

FUSE.

SYSTEM: D&C SUBSYSTEM ASS'Y P/N: 51140E391

SHEET: RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS TESTING (FOR INSULATION RESISTANCE, DIELECTRIC STRENGTH, AND MOUNTING OF THE SWITCH TO THE D&C PANEL IS BY MEANS OF A 15/32 MUT WHICH ENGAGES A THREADED BUSHING ON THE SWITCH. A KEYED WASHER PROVIDES ROTATION RESTRAINT. AFTER INSTALLATION AND TORQUING, THE NUT IS STAKED TO THE PANEL BY A BLOB OF EPOXY ADHESIVE. A STAINLESS STEEL GUARD PROTECTS THE SWITCH LEVER AGAINST DAMAGE OR INADVERTENT OPERATION.

BE HARDWIRE ED 85511 CONTACT SAFED AND SHORTS TO CASE (MODE, BRAKES WILL BE ANALYSIS OF THE BASIC PANEL STRUCTURE HAS DEMONSTRATED THAT THERE ARE NO RESONANCES IN THE RELEVANT VIBRATION FREDUENCY SPECTRUM, THIS ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING BRAKE, SAFING). APPLIED. LIMPING LOST DURING END EFFECTOR OF THE D&C PAMEL ASSEMBLY. CAPTURE. APPLICATION ANALYSIS HAS CONFIRMED THAT ADEQUATE ELECTRICAL LOSS OF EE STRESS MARGINS ARE ACHIEVED. PRIMARY DRIVE AT THE PART LEVEL, QUALIFICATION/CERTIFICATION TESTING IS DEFINED BY ROCKWELL INTERNATIONAL SPECIFICATION MC452-0102. HODES. WORST CASE THIS TEST REQUIREMENT INCLUDES: INSULATION RESISTANCE DIELECTRIC STRENGTH, CONTACT RESISTANCE, RANDOM VIBRATION (48 MINUTES PER AKIS), LÉAKAGE AT ONE ATMOSPHERE DIFFERENTIAL LOSS OF MISSION PRESSURE, TOGGLE STRENGTH. FOR SWITCH OPERATIONAL CYCLES REFER TO TABLE 13. LOSS OF PRIMARY HODES. ALL UNITS ARE SUBJECTED TO ACCEPTANCE TESTS WHICH INCLUDE PRE-ACCEPTANCE RUN-IN, DIELECTRIC STRENGTH, INSTALLATION RESISTANCE, CONTACT RESISTANCE, ACCEPTANCE VIBRATION, SEAL REDUNDANT PATHS REMAINING TEST, VISUAL EXAMENATION, AND RADIOGRAPHIC INSPECTION. BACKUP CIL REV: 3 SUPERCEDING DATE: 06 OCT 87 DATE: 24 JUL 91 PREPARED BY: HFWG

RMS/D&C - 318

PREPARED BY:

HFWG

PROJECT: SRMS (-5 MCIU INSTALLED)
ASS'Y NOMENCLATURE: DEC PANEL SYSTEM: DEC SUBSYSTEM SHFET: ____3 ASS'Y P/N: 51140E391 NAME, OTY, & FAILURE EFFECT **FMEA** FREA FAILURE MODE HDWR / FUNC. RATIONALE FOR ACCEPTANCE DRAWING REF. REF. REV. AND 2/1R DESIGNATION CAUSE END ITEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS 1400 3 28V POWER MODE: WILL BLOW 2 AMP ACCEPTANCE TESTS LOSS OF 28V SUPPLY FUSE. 011-1 DC. LOSS OF PRIMARY THE HARDWARE ITEM IS SUBJECTED TO THE FOLLOWING ACCEPTANCE CORBITER POWER. GPC ENVIRONMENTAL TESTING AS PART OF THE DEC PANEL. SYSTEM). CAUSE(S): TERMINATES 1/O. (1) ANY 28V MCIU SHUTS PS 90128. O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1 SWITCH WL 90120. DOWN. ARM WILL BE HARDWIRE ED 85511 CONTACT O THERMAL: +100 DEGREES F TO +10 DEGREES F 2 CYCLES SHORTS TO SAFED AND (9.5 HRS PER CYCLE) CASE (MODE, BRAKES WILL BE BRAKE, APPLIED. THE D&C PANEL ASSEMBLY IS FURTHER TESTED AS PART OF THE RMS SAFING). LIMPING LOST SYSTEM (TP518 RMS STRONGBACK TEST AND TP552 FLAT FLOOR TEST) DURING END WHICH VERIFIES THE ABSENCE OF THE FAILURE MODE. EFFECTOR CAPTURE. QUALIFICATION TESTS LOSS OF EE THE DEC PANEL HAS BEEN SUBJECTED TO THE FOLLOWING PRIMARY DRIVE QUALIFICATION TEST ENVIRONMENT: MODES. O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1
O SHOCK: 20G/11MS - 3 AKES (6 DIRECTION)
O THERMAL: 130 DEGREES F TO -23 DEGREES F (12 MRS WORST CASE PER CYCLE) (6 CYCLES) LOSS OF MISSION O MUNICITY: 95% (120 DEGREES F TO 82 DEGREES F CYCLE IN LOSS OF PRIMARY 16 HRS) 10 CYCLES TOTAL MIL-STD-461 AS MODIFIED BY SL-E-0002 (TEST CEO1, CE MODES. O EHC: CEO3, CSO1(DC/AC), CSO2, CSO6, REO2 (B/M), RSO2, RSO3, RSO4) REOZ (B/M) RSO2, O3, O4) REDUNDANT PATHS REMAINING BACKUP FLIGHT CHECKOUT PORS OPS CHECKLIST (ALL VEHICLES) JSC 16987

APPROVED BY:

DATE: <u>24 JUL 91</u>

CIL REV: _3

SUPERCEDING DATE: 06 OCT 87

DESIGNATION 28V POWER SUPPLY OIT-1 (ORBITER SYSTEM). PS 90128. WL 90128. ED 85511	MODE: LOSS OF 2BV DC. CAUSE(S): (1) ANY 2BV SWITCH CONIACT SHORTS TO CASE (MODE, BRAKES SAFING). WILL B FUSE. LOSS OF POWER. TERMINI MCIU SI BE HAR SAFED / BRAKES APPLIE LIMPINI DURING EFFECTI CAPTURE LOSS OF LO	BLOW 2 AMP OF PRIMARY R. GPC INATES 1/O. I SHUIS . ARM WILL ARDWIRE D AND ES WILL BE IED. ING LOST NG END CTOR URE.	OA/INSPECTIONS HERMETICALLY SEALED TOGGLE SWITCHES ARE PROCURED TO ROCKWELL SPECIFICATION MC452-0102. ROCKWELL PART NO. MC452-0102 OUALIFICATION AND ACCEPTANCE TESTING OF SWITCHES IS PERFORMED TO R.I. SPEC. MC452-0102. HERMETICALLY SEALED ROTARY SWITCHES ARE PROCURED TO ROCKWELL SPEC MC452-0049, AS REQUIRED BY THE APPLICABLE CAE SPECIFICATION. OUALIFICATION AND ACCEPTANCE TESTING OF SWITCHES PERFORMED TO RI SPEC MC452-0049. WIRE IS PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-W-81381
	MODES,	ARY DRIVE S. T CASE OF MISSION OF PRIMARY S. HDANT PATHS INING	AND INSPECTED AND TESTED TO MASA JSCM8080 STANDARD NUMBER 95A. RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE HAS OCCURRED TO PARTS DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS. PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE, COMPONENT MOUNTING TO FRONT PANEL INSPECTION, SOLDERING OF WIRES TO SWITCH CONTACTS, WIRE ROUTING, STRESS RELIEF OF WIRES FIC., OPERATORS AND INSPECTIORS ARE TRAINED AND CERTIFIED TO MASA MHB 5300.4(3A) STANDARD, AS MODIFIED BY JSCO8800A. PRE-TEST INSPECTION OF D&C PANEL ASSY INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILD CONFIGURATION VERIFICATION TO AS DESIGN ETC. (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT) A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST OCCUMENTS, TEST EQUIPMENT CALIBRATION/VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVENED BY OUALITY ASSURANCE IN CONJUNCTION WITH ENGINEERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ATP) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT). INTEGRATION OF D&C PANEL, RHC, THC AND MCIU, INSPECTIONS ARE PERFORMED AT EACH STAGE OF INTEGRATION, WHICH INCLUDES GROWNOING CHECKS, INTER CONNECT CABLE VERTIFICATION, CONNECTOR INSPECTION FOR BENT OR PUSHBACK CONTACTS ETC. SUB-SYSTEM PERFORMANCE TESTING (ATP), INCLUDES AN AMBIENT PERFORMANCE TEST. (MANDATORY INSPECTION POINT).

PRINCET: SRMS (-5 MCIU INSTALLED)
ASS'Y NOMENCLATURE: DEC PANEL

SYSIEM: DEC SUBSYSIEM
ASS'Y P/N: 51140E391 SHEET: 5

	FMEA REV,	NAME, GTY, B DRAWING REF. DESIGNATION	FAILURE MODE - AND CAUSE	FAILURE EFFECT ON END ITEM	HDUR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
1400	3	28V POWER SUPPLY OIY-1 (ORBITER SYSTEM). PS 90128. UL 90128. ED 65511	MODE: LOSS OF 28V DC. CAUSE(S): (1) ANY 28V SWITCH CONTACT SHORTS TO CASE (MODE, BRAKE, SAFFNG).	WILL BLOW 2 AMP FUSE. LOSS OF PRIMARY POWER. GPC ITEMINATES I/O. MCIU SHUTS DOWN. ARM WILL BE HAROWIRE SAFED AND BRAKES WILL BE APPLIED. LIMPING LOST DURING END EFFECTOR CAPTURE. LOSS OF EE PRIMARY DRIVE MODES. WORST CASE LOSS OF MISSION LOSS OF PRIMARY MODES. REDWINDANT PATHS REMAINING BACKUP	SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTERACTION MICH INCLUDES GROUNDING CHECKS, THRU MITING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC. SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT) ON THE PROPERTY OF THE PRO
REPARED BY	: #	IF MG	SUPERCEDING DAT	E: 06 0C1 87	APPROVED BY: DATE: 24 JUL 91 CIL REV

PREPARED BY:

MFWG

PROJECT: SRMS (-5 HCTU INSTALLED)
ASS'Y NOMERCEATURE: DEC PAREL SYSILM: DEC SUBSYSTEM ASS'Y P/N: 51140E391 SHEET: __6 NAME, OTY, & DRAWING REF. FMEA FAILURE MODE HDWR / FUNC. 2/1R FAILURE EFFECT RATIONALE FOR ACCEPTANCE REF. REV. AND ON DESIGNATION CAUSE END ITEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS 1400 3 28V POWER MODE: WILL BLOW 2 ANP FAILURE HISTORY SUPPLY LOSS OF 28V FUSE. 01Y-1 LOSS OF PRIMARY DC. POWER. GPC TERMINATES 1/0. (ORBLIER THERE HAVE BEEN NO FAILURES ASSOCIATED WITH THIS FAILURE SYSTEM). CAUSE(S): HODE ON THE SRMS PROGRAM. PS 90128. (1) ANY 28V MCIU SHUTS WL 90128. SWITCH DOWN. ARM WILL BE HARDWIRE ED 85511 CONTACT SHORTS TO SAFED AND BRAKES WILL BE CASE (MODE, BRAKE, SAFING). APPLIED. LIMPING LOST DURING END EFFECTOR CAPTURE. LOSS OF EE PRIMARY DRIVE MODES. WORST CASE LOSS OF HISSION LOSS OF PRIMARY MODES. REDUNDANT PATHS REMAINING BACKUP

DATE: 24 JUL 91

CIL REV: 3

SUPERCEDING DATE: 06 OCT B7

ASS'Y NUMERICATURE: DEC PAREL ASS'Y PURE STREET

REF. REV.	HAME, GIY, & DRAWING REF. DESIGNATION	AND CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
1400	28Y POWER SUPPLY 01Y-1 (ORBITER SYSTEM). PS 90128 WL 90128. ED 85511	HODE: LOSS OF 28V DC. CAUSE(S): (1) ANY 28V SMITCH CONTACT SHORTS TO CASE (MODE, BRAKE, SAFING).	WILL BLOW 2 AMP FUSE. LOSS OF PRIMARY POWER. GPC TERMINATES I/O. MCIU SHUTS DOWN. ARM WILL BE HARDWIRE SAFED AND BRAKES WILL BE APPLIED. LIMPING LOST DURING END EFFECTOR CAPTURE. LOSS OF EE PRIMARY DRIVE MODES. WORST CASE LOSS OF MISSION LOSS OF PRIMARY MODES. REDUNDANT PATHS REMAINING BACKUP	OPERATIONAL EFFECTS PRIMARY MODES CANNOT BE USED TO COMPLETE THE MISSION. BACKUP MODE AVAILABLE. IF PAYLOAD ATTACHED ARM SHOULD BE MANELVERED TO A SAFE POSITION FOR PAYLOAD RELEASE. IF SUBSEQUENT FAILURE OCCURS ALL DRIVE MODES ARE LOST. THE ARM MAY BE JETTISONED. CREW ACTION USE BACKUP. CREW TRAINING NONE MISSION CONSTRAINT NONE WITH SAFING SWITCH IN 'AUTO' VERIFY VOLTAGE AT LONGERON INTERFACE. OMRSD ONLINE INSTALLATION WITH SAFING SWITCH IN 'AUTO' VERIFY VOLTAGE AT LONGERON INTERFACE. OMRSD ONLINE TURNAROUND WITH SAFING SWITCH IN AUTO' SELECT SINGLE AND DRIVE ANY JOINT. VERIFY TACHOMETER SIGNATURE.